

WESTERN REGION  
HISTORIC AMERICAN ENGINEERING RECORD

INDEX TO PHOTOGRAPHS

HAER  
CAL,  
I-LIVMO.V,  
I-

Carroll Overhead Bridge  
Altamont Pass Road,  
east of Livermore  
Alameda County  
California

HAER No. CA-52

Ed Andersen, Photographer, January 31, 1987  
John Snyder, Field Director

PHOTOGRAPHS

- CA-52 -1 Contextual overview; view to north from Interstate Highway 5 viaduct (I-5 replaced Altamont Pass Road); Carroll Road at right; 65mm lens.
- CA-52 -2 Contextual overview; view to north from Interstate Highway 5 viaduct; 90mm lens.
- CA-52 -3 Contextual overview; view northwest from Carroll Road; 65mm lens.
- CA-52 -4 Southeast elevation; note collision walls where railroad passes beneath bridge; view to west-northwest; 65mm lens.
- CA-52 -5 Oblique view of southeast elevation; view to north; 65mm lens.
- CA-52 -6 View along alignment of former Southern Pacific Railroad right of way; Altamont Creek at left between railroad and bridge; view to northeast; 90mm lens.
- CA-52 -7 North elevation from shoulder of Altamont Pass Road; Interstate Highway 5 viaduct in background; former Western Pacific (now Union Pacific) Railroad at right; abandoned Southern Pacific right of way beneath bridge; view to southwest; 90mm lens.
- CA-52 -8 Deck view, east approach; intersection of Carroll Road at left; Interstate Highway 5 viaduct in background; view to southwest; 90mm lens.
- CA-52 -9 Oblique view of southeast elevation; view to west; 65mm lens.

Carroll Overhead Bridge  
HAER No. CA-52  
Index to Photographs  
Page 2

- CA- 52-10 Deck view, west approach; former Western Pacific (now Union Pacific) Railroad at left; wind turbine generators atop hill in background; view to northeast; 90mm lens.
- CA- 52-11 View along former Western Pacific (now Union Pacific) Railroad; view to northeast; 90mm lens.
- CA- 52-12 View along alignment of former Southern Pacific Railroad right of way; note collision walls, provision for two tracks; view to north-northeast; 90mm lens.
- CA- 52-13 View depicting arrangement of bents, curved alignment, from point of crossing of former Southern Pacific right of way; collision wall at right; view to southwest; 90mm lens.
- CA- 52-14 Detail, typical span; note spalling below parapet railing; view to northwest; 135mm lens.
- CA- 52-15 View depicting reverse-curved alignment; view to northeast; 90mm lens.
- CA- 52-16 Detail, typical expansion joint; view to east; 135mm lens.
- CA- 52-17 View along centerline from beneath bridge; view to northeast; 90mm lens.
- CA- 52-18 View of east abutment from beneath bridge; view to northeast; 90mm lens.

HISTORIC PHOTOGRAPHS - PHOTOCOPIES OF PHOTOGRAPHS

- CA- 52-19 View to southwest along bridge alignment, showing reverse curve; photographer unknown; 1933 photo from collection of Office of Structures Maintenance, California Department of Transportation, Sacramento.
- CA- 52-20 View to southwest along bridge alignment, showing reverse curve from near deck level; Southern Pacific Railroad track passing beneath bridge; Western Pacific Railroad track out of sight behind bridge; photographer unknown; 1933 photo from collection of Office of Structures Maintenance, California Department of Transportation, Sacramento.